

50c 70 02 12

25X1 25X1

T O P S E C R E T 6561597 DEC 76 CITE 9947

SUBJECT: ERROR IN CFC PARAMETERS CONCERNING THE CLOCK CORRELATION PAPAMETERS IN MPR

1. THE LATEST TRANSMISSION TAP FOR MISSION PERFORMANCE REPORT STILL CONTAINS 18 DIGITS IN THE CFC PARAMETER FOR CLOCK CORRELATION. THIS DOES NOT AGREE WITH THE SPECIFICATIONS WHICH SHOW ONLY 11 DIGITS FOR THIS NUMBER, COLUMN 102-112. THIS ITEM IS DESCRIBED AS VEHICLE CLOCK CALIBRATION COFFICIENT C COMPUTED BY S CLOCK.

2. OUR VERSION OF S CLOCK DOES NOT SHOW ANY NUMBER OF THE MAGNITUDE FOR THE NUMBER IN THE TRANSMISSION AND WE HAVE NO DOCUMENTATION

SHOWING ANY CHANGE IN THIS NUMBER.

3. IT IS REQUESTED THAT THE 18DIGIT NUMBER BE EXPLAINED AND THE LATEST DOCUMENTATION FOR S CLOCK BE TRANSMITTED TO AS SOON 25 AS POSSIBLE.

TOPSECRET

BE TRANSMITTED TO AS SOON 25X1

EOM GROUP ONE CX PI

3 /MED L

-25X1